

**Flood Control Project Maintenance**  
**Levee Inspections**  
**Levee Log Report By Levee Mile - Updated 8/23/2021**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspector
Unit No. 01 Mellin Levee	Right	0.59	Dustin Sanoski

Entry No	Levee Mile		Category	Item	Location	Comment	Source
	Start	End					Permits
17	0.00	0.00	Aerial	High Voltage	Crossing	Overhead utility line crosses levee with inadequate overhead clearance 20 ft above crown. Utility poles are more than 15 ft away from the levee toes. Entry Last Updated : 12/29/2020	USACEINSPECT
1	0.00	0.58	At Grade	Road / Highway	Crossing	Roadway on waterward berm. Entry Last Updated : 1/22/2018	GEILEVEELOG
2	0.00	0.00	Mark	Boundary	Crown	Start of levee section at State Highway No. 84 about 1 mile north of Rio Vista. Levee constructed in 1971 by U. S. Corps of Engineers. 20-foot graveled crown roadway. Levee mileage runs westerly. Entry Last Updated : 1/22/2018	GEILEVEELOG
3	0.01	0.01	Miscellaneous	Other	Land Side	Fire hydrant on LS slope. Entry Last Updated : 1/30/2018	LEVEELOG
18	0.01	0.01	Gate	Cable	Crown	Access gate across crown. Two 6 inch pipe bollard gate posts. Cable gate unlocked during inspection. One steel fence segment on LS. Entry Last Updated : 12/29/2020	USACEINSPECT
22	0.01	0.59	Fence	Barbed Wire	Water Side	Barbed wire fence along WS hinge. Fence is mounted on wood and T-posts. Woven and barbed wire fence from WS hinge to beyond 15 ft from WS toe at this location. Entry Last Updated : 12/29/2020	USACEINSPECT
5	0.07	0.07	Fence	Metal	Water Side	Cross fence. Entry Last Updated : 12/29/2020	GEILEVEELOG 10340
11	0.07	0.07	Fence	Metal	Land Side	Cross fence. Entry Last Updated : 12/29/2020	LEVEELOG 10340
7	0.08	0.08	Non-Project Levee	Spur	Land Side	Spur levee on LS slope. Entry Last Updated : 1/30/2018	LEVEELOG
6	0.09	0.28	Fence	Barbed Wire	Land Side	Fence along landward slope of levee. Entry Last Updated : 12/29/2020	GEILEVEELOG
15	0.14	0.14	Wall	Concrete / Masonry Wall	Land Side	Temporary concrete barricade creates wall runnign down LS slope to toe Entry Last Updated : 1/30/2018	LEVEELOG

**Flood Control Project Maintenance  
Levee Inspections  
Levee Log Report By Levee Mile - Updated 8/23/2021**

**Solano County Public Works Mellin Levee**

Waterway							Bank	Unit Miles	Inspector
Unit No. 01 Mellin Levee							Right	0.59	Dustin Sanoski
Entry No	Levee Mile		Category	Item	Location	Comment	Source		
	Start	End					Permits		
35	0.14	0.14	Ramp	Ramp	Land Side	Access ramp on LS slope to DWR property. Ramp is 30 ft wide and gravel surfaced. LMA indicates that ramp was built by DWR. Entry Last Updated : 12/29/2020	USACEINSPECT		
36	0.14	0.14	Gate	Metal	Land Side	Fence along each side of ramp Entry Last Updated : 12/29/2020	USACEINSPECT		
19	0.15	0.59	At Grade	Levee	Crown	Gravel road ends. Grass covered levee road continues. Entry Last Updated : 1/30/2018	LEEVEELOG		
20	0.17	0.17	Barrier	Concrete	Land Side	Temporary concrete barricade creates wall runnign down LS slope to toe Entry Last Updated : 1/30/2018	LEEVEELOG		
14	0.28	0.28	Fence	Barbed Wire	Water Side	Wire mesh and barbed wire fence on WS slope. 6 inch by 8 inch fence posts and t posts. Entry Last Updated : 12/29/2020	LEEVEELOG		
16	0.28	0.28	Gate	Metal	Crown	Wire mesh and barbed wire fence on WS slope. 6 inch by 8 inch fence posts and t posts. Entry Last Updated : 12/29/2020	LEEVEELOG		
41	0.28	0.28	Barrier	Concrete	Land Side	20 ft long K-rail/Jersey barrier on LS slope. Entry Last Updated : 12/29/2020	USACEINSPECT		
42	0.31	0.59	Fence	Barbed Wire	Water Side	5 strand barbed wire fence from WS hinge to WS toe on T-posts and pipe posts. 10 ft wide steel pipe gate from 5 to 15 ft beyond WS toe. Fence continues along WS toe. Entry Last Updated : 12/29/2020	USACEINSPECT		
8	0.36	0.36	Ramp	Ramp	Land Side	Ramp on LS slope. Entry Last Updated : 1/30/2018	LEEVEELOG		
9	0.45	0.45	Miscellaneous	Turnouts	Land Side	Turnaround on landward shoulder. Entry Last Updated : 1/22/2018	GEILEVEELOG		
10	0.52	0.52	Gate	Metal	Water Side	Metal and barbed wire runs down slope with metal gate at LS toe. Entry Last Updated : 1/30/2018	LEEVEELOG		
21	0.52	0.52	Fence	Barbed Wire	Land Side	Metal and barbed wire runs down slope with metal gate at LS toe. Entry Last Updated : 12/29/2020	LEEVEELOG		

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Log Report By Levee Mile - Updated 8/23/2021**

**Solano County Public Works Mellin Levee**

Waterway	Bank	Unit Miles	Inspector
Unit No. 01 Mellin Levee	Right	0.59	Dustin Sanoski

Entry No	Levee Mile		Category	Item	Location	Comment	Source
	Start	End					Permits

47	0.56	0.59	Fence	Chain Link	Water Side	Corral on WS from hinge to beyond 15 ft from WS toe. Corral includes: Steel pipe gate fencing with wood posts, tank with 2 inch piping and hose, metal trough and wood beam supports. Entry Last Updated : 12/29/2020	USACEINSPECT
----	------	------	-------	------------	------------	---	--------------

12	0.56	0.56	Ramp	Ramp	Land Side	Turnaround and Ramp on landward slope. Entry Last Updated : 1/22/2018	GEILEVEELOG
----	------	------	------	------	-----------	--	-------------

13	0.59	0.59	Mark	Boundary	Crown	End of Unit. Entry Last Updated : 1/22/2018	GEILEVEELOG
----	------	------	------	----------	-------	--	-------------